JAN 2 5 1982 FORM Approved OMB No. 44-R1387

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

MATERIAL SAFETY

Required under USDL Safety and Health Regulations for Ship Repairing,

Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)								
SECTION I								
MANUFACTURER'S NAME EMERGENCY TELEPHO (213) 537-76								
ADDRESS (Number, Street, City, State, and ZIP Cool 19451 Susana Rd., Compton	de) (CA 902	2 1					
CHEMICAL NAME AND SYNONYMS N/A TRADE NAME AND SYNONYMS Pro-Seal 501 Acceler								
CHEMICAL FAMILY Diluted oxidizer			FORMULA N/A					
SECTION II - HAZARDOUS INGREDIENTS								
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)			
PIGMENTS			BASE METAL					
catalystDimethy benzyl hydro			ALLOYS					
vehicle peroxide 20-25%			METALLIC COATINGS					
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX					
ADDITIVES			OTHERS					
OTHERS								
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES								
					1			
	-							
SEC	TIO	N III - P	HYSICAL DATA					
BOILING POINT (°F.)	1_	N/A	SPECIFIC GRAVITY (H2O=1)		1.1			
VAPOR PRESSURE (mm Hg.)	\perp	N/A	PERCENT, VOLATILE BY VOLUME (%)		0			
VAPOR DENSITY (AIR=1)		N/A	EVAPORATION RATE (=1)		/A			
SOLUBILITY IN WATER	1	Nil						
APPEARANCE AND ODOR Viscous clear liquid-faintly sweet odor.								
SECTION IV	FIR	FANDE	EXPLOSION HAZARD DATA		-			
SLASH POINT (Malbod word)		·	FLAMMABLE LIMITS Lei		Uel			
180 F closed cup N/A								
Dry chemical, CO, Foam, water SPECIAL FIRE FIGHTING PROCEDURES 2								
None								
UNUŞUAL FIRE AND EXPLOSION HAZARDS								
Choyone i the And Excession thanks	_N.c	ne			···			

				···				
SECTION V - HEALTH HAZARD DATA								
THRESHOLD LIMIT VALUE Unknown								
EFFECTS OF OVEREXPOSURE May cause irritation of skin or mucous membranes.								
		<u></u>						
EMERGENCY AND FIRST AID PROCEDURES If skin contact occurs wash with soap and water.								
If skin contact occurs wash with soap and water. If eye contact occurs, flush thoroughly with water, and consult								
physician.								
		SECTION	VI - R	EACTIVITY DA	TA \			
STABILITY	UNSTABLE	CONDITIONS TO AVOID						
	STABLE	ABLE X High temperature						
INCOMPATABILITY (Materials to avoid) Avoid strong reducing agents.								
HAZARDOUS DECOMPOSITION PRODUCTS CO,, H ₂ O upon combustion.								
MAY OCCUP CONDITION				CONDITIONS TO				
HAZARDOUS POLYMERIZATION	WILL NOT	CCUR	Х					
	SECT	ION VII	- SPILL	OR LEAK PROC	EDURES			
steps to be taken in case material is released or spilled Clean up spillage with rags or sweeping compound and solvents.								
OTEAN UP	<u>SPITIUGE</u>	· · · · · · · · · · · · · · · · · · ·		<u> </u>				
			,					
WASTE DISPOSAL	METHOD Prefer	ably b	urn wa	ste or reac	t with base and			
dispose	s inert mat	erial.			:			
	SECTION	VIII - SF	PECIAL	PROTECTION IN	IFORMATION			
RESPIRATORY PRO	TECTION (Specify 1)	<i>'pc)</i> In c	onfine	ed areas, ca	nnister type.			
VENTILATION LOCAL EXHAUST Recommended					SPECIAL			
••	MECHANICAL (Ge				OTHER			
PROTECTIVE GLOV	l VES Neoprene			EYE PROTECTION	Safety glasses.			
OTHER PROTECTIVE EQUIPMENT Coveralls, aprons								
		Verail	.υ, αρι					
SECTION IX - SPECIAL PRECAUTIONS								
PRECAUTIONS TO	BE TAKEN IN HANE	LING AND	STORING	Avoid contro	ct and ingestion. Store			
below 80	F.			AVOIU CONTAC	r and ingestion, store			
OTHER PRECAUTI	ONS		-					
	None							
1								

GPO 934-110